

Quick Start Guide

Workstation Setup


1. Connect all peripheral devices to the docking station.



2. Connect the CMS Universal Docking Station to your host device.



Docking Station Diagram



System Requirements

Hardware

- Thunderbolt 3 or USB-C port
- Power Delivery charging support requires host computer
- Support Power Delivery 2.0 charging (up to 100W max)

Operating System (any of the following)

- Microsoft Windows® 7, Windows® 8, Windows® 8.1, or Windows® 10 (32/64-bit)
- Mac OS® X v10.8 or later
- Android 5.0 or later
- Chromebooks
- Ubuntu 14.04.x LTS and 16.04 LTS on x86 platform